

FIG. -1-

10000000000000000000000000000000




FIG. -2-




FIG. -3-




FIG. -4-




FIG. -5A-

10000000000000000000000000000000




FIG. -5B-




FIG. -6-

RESISTANCE TO ABRASION AND PUNCTURE HAZARDS
ABRASION TESTING

RESISTANCE TO ABRASION BY GRAVEL




FIG. - 7-

RESISTANCE TO ABRASION AND PUNCTURE HAZARDS
ABRASION TESTING

RESISTANCE TO ABRASION ON CONCRETE




FIG. -8-

RESISTANCE TO ABRASION AND PUNCTURE HAZARDS
PUNCTURE TESTING

TEST MEDIA

- SHARDS OF SIDE WINDOW GLASS

TEST METHOD

- DEPLOY TEST BAG TO 30 psi AGAINST PLATE COVERD WITH BROKEN GLASS.
- DROP 25 lb WEIGHT ON PLATE AS BAG REACHES FULL INFLATION.

TEST MEASUREMENT

- MEASURE TIME TO FALL FROM 30 psi TO 15 psi.




FIG. -9-




FIG. -10-




FIG. -11-




FIG. -12A-




FIG. -12B-




FIG. -12C-




FIG. -12D-




FIG. -12E-




FIG. -12F-




FIG. -12G-




FIG. -12H-




FIG. -12I-




FIG. -12J-




FIG. -12K-




FIG. -12L-




FIG. -12M-